

ANGELINA COUNTY TEXAS HISTORIC SURVEY

Porch Loc.
 Porch Roof
 Porch Support
 Hist. Context

Integrity Location Yes
 Materials Yes
 Setting Yes
 Association Yes

Public Access Yes

Threatened

Threat

Ancillary Structure #1 Type

Roof Form Roof Matls

Wall Matls

Site Extras Sidewalks No
 Drives No
 Gardens No

Terracing No

Well/Cistern No

Other

Owner Name

Address

City

Zip

State

Status

Notes:

The 1986 survey lists this property as 100 West Burke, in 2016 is 110 West Burke Street.

Log Structure List

- Single-pen Double-pen
 Saddlebag Dogtrot

Vernacular House Form List

- Hall-and-parlor (1 story) I-house (2 story)
 Shotgun (1 story) Town house (2 story)
 Massed side-gable (1) Box house (2 story)
 Massed gable-front (1) Gable front (2 story)
 Four-square (1 story) Four-square (2 story)
 Gable-front-and-wing (1) Gable-front-and-wing (2)
 Front-facing U or H (1) Front-facing U or H (2)

Overall Condition

- Excellent
 Good
 Fair
 Poor
 Bad
 Vacant
 Gone

Commercial Form List

- One-Part Commercial Block
 Two-Part Commercial Block
 Enframed Window Wall
 Stacked Vertical Block
 Two-Part Vertical Block
 Three-Part Vertical Block
 Temple Front
 Enframed Block
 Central Block with Wings
 Arcaded Block
 Mixed

(based on Longstreth)

Reference Image