City of Nacogdoches Historic Survey Form New New Delete Find

Name Sterne-Hoya DistricT	Commercial Types	Non-House Date/Vernacular Date
Address 536 E Pilar St Recorded by Natalie Bach Date Surveyed 7/28/2011 Overall Condition	☐ One-Part C. Block ☐ Temple Front ☐ Two-Part C. Block ☐ Temple Front ☐ Enframed Window Wall ☐ Enframed Block ☐ Stacked Vertical Block ☐ Central Block with Wings ☐ Two-Part Vertical Block ☐ Arcaded Block ☐ Three-Part Vertical Block ☐ Mix	 1. 1820-1865 ≥ 2. 1865-1900 ⇒ 3. 1900-1929 ⇒ 4. 1929-1945 ⇒ 5. 1945-1980 ⇒ 6. 1980-today
Roof Type Gable Shed Dormers - Gable Hipped Flat Dormers - Hipped Gambrel Other Dormers - Shed Roof Materials Wood shingles Tile Other	Agricultural Mfg/Industrial Religious Social Social State Marker Civic/Government Other Marker Transportation Commercial Outbuilding Domestic Parks/Gardens/Plantings Educational Petroleum Petroleum Commercial Commercia	Outbuildings Garage Shed Barn Other Other Chimney
Roof Condition Excellent Good Fair Poor Bad Wall Facade	Local Marker Recreational/Cultural Hall-and-parlor (1story) Gable-front-and-wing (1) Gable front Shotgun (1 story) Front-facing U or H (1) Four-square Massed side-gable (1) I-house (2 story) Gable-front Massed gable-front (1) Town house (2 story) Front-facin Four-square (1 story) Box house (2 story)	(2 story) e (2 story) -and-wing (2)
Stucco Other Number of bays Stone Vinyl Siding Terracota Brick Fieldstone V. Awning(s) Log Wood Siding Metal Wood Shingle Numbers of bays 1 2 3 4 5 Other	02. Fr. Colon. 1608-1830	Internat. 1925-today Minimal Trad. 1935-60 A-Frame 1930s-present Sm. Ranch 1946-1980 Lg. Ranch 1946-1980 Split-L 1955-1980 Contemp. 1940-1980 Shed 1960-today Neoeclect 1965-today
Wall Condition ⊠ Excellent □ Good □ Fair □ Poor □ Bad	☐ 10. RRoman R 1870s-1890s ☐ 23. Craftsman 1900-1930 ☐ 36.	Prefab H 1940s-1950s Mobile H 1945-today