City of Nacogdoches Historic Survey Form

Name jms_613 Logansport	Commercial Types	Non-House Date/Vernacular Date
Address 613 Logansport Recorded by Misty Date Surveyed 8/2/2011 Overall Condition Image: Excellent Good Fair Poor Bad	One-Part C. Block Temple Front Two-Part C. Block Temple Front Enframed Window Wall Enframed Block Stacked Vertical Block Central Block with Wings Two-Part Vertical Block Arcaded Block Three-Part Vertical Block Mix	 1. 1820-1865 2. 1865-1900 3. 1900-1929 4. 1929-1945 5. 1945-1980 6. 1980-today
Roof Type Gable Shed Dormers - Gable Hipped Flat Dormers - Hipped Gambrel Other Dormers - Shed Roof Materials Wood shingles Tile Other Other		Outbuildings Garage Shed Barn Other Other Chimney Porch
Roof Condition Xerial Excellent Good Fair Poor Bad Wall Facade	□ Hall-and-parlor (1story)□ Gable-front-and-wing (1)□ Gable front (2)□ Shotgun (1 story)□ Front-facing U or H (1)□ Four-square (1)□ Massed side-gable (1)□ I-house (2 story)□ Gable-front-a□ Massed gable-front (1)□ Town house (2 story)□ Front-facing U□ Four-square (1 story)□ Box house (2 story)□ Front-facing U	(2 story) and-wing (2)
Stucco Other Number of bays Stone Vinyl Siding Terracota Brick Fieldstone V. Awning(s) Log Wood Siding Metal Wood Shingle	02. Fr. Colon. 1608-1830 15. Beaux Arts 1885-1930 28. Min 03. Greek Rev. 1820-1860 16. Fr. Rev. 1880s-1940s 29. A-1 04. Gothic Rev. 1830s-70s 17. Ital. Ren 1880-1935 29. Sm 05. Italianate 1840s-80s 18. Mission 1890-1920 30. Lg	ternat. 1925-today nimal Trad. 1935-60 Frame 1930s-present n. Ranch 1946-1980 . Ranch 1946-1980 Ilit-L 1955-1980
Numbers of bays 1 2 3 4 5 Other Wall Condition Wall Condition Excellent Good Fair Poor Bad	07. Stick Style 1860s-80s 20. Sp. Eclectic 1915-40 32. Co 08. Q. Anne 1880-1910 21. Monterey 1925-1955 33. Sh 09. Shingle 1880-1900 22. Prairie 1900s-1920s 34. Ne 10. RRoman R 1870s-1890s 23. Craftsman 1900-1930 36. Pre	ntemp. 1940-1980 ed 1960-today eoeclect 1965-today efab H 1940s-1950s obile H 1945-today