

VOICES FROM SMALL PLACES HISTORIC SURVEY

| | | | |
|----------------|--|--------------|--|
| Project # | CRHR-001 | Property # | 002 |
| County | Shelby | City | Arcadia |
| Address | Corner CR 138 & CR 4064 | | |
| Recorded By | Kelley Snowden | Date | 7/25/2014 |
| Current Name | | | |
| Historic Name | Cooper School Consolidated | | |
| Date Const | | Estimated | |
| Actual | | Modified | |
| Roof Type | <input type="checkbox"/> Gable <input type="checkbox"/> Gambrel <input type="checkbox"/> Flat <input type="checkbox"/> Hipped <input type="checkbox"/> Shed <input type="checkbox"/> Other | | |
| Roof Materials | <input type="checkbox"/> Wood Shingles <input type="checkbox"/> Tile <input type="checkbox"/> Other <input type="checkbox"/> Composition Shingles <input type="checkbox"/> Metal | | |
| Roof Condition | <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Bad | | |
| # of Dormers | | Dormer Type | <input type="checkbox"/> None <input type="checkbox"/> Eyebrow <input type="checkbox"/> Gabled <input type="checkbox"/> Inset <input type="checkbox"/> Hipped <input type="checkbox"/> Other <input type="checkbox"/> Shed <input type="checkbox"/> Flat <input type="checkbox"/> Deck <input type="checkbox"/> Arched |
| Wall Materials | <input type="checkbox"/> Stucco <input type="checkbox"/> Other <input type="checkbox"/> Stone <input type="checkbox"/> Vinyl Siding <input type="checkbox"/> Brick <input type="checkbox"/> Fieldstone V. <input type="checkbox"/> Log <input type="checkbox"/> Wood Siding <input type="checkbox"/> Metal <input type="checkbox"/> Wood Shingle | | |
| Wall Condition | <input type="checkbox"/> Excellent <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Bad | | |
| Window Type | | | |
| Window Mat | | | |
| Orig Windows | | | |
| Single Door | | Double Door | |
| Transom | | Sidelights | |
| # of Stories | | Basement | |
| Foundation | | # of Bays | |
| Bldg Plan | | | |
| # of Chimneys | | Chimney Type | |
| Chimney Mat | | | |

Resources Type List

- | | | |
|---|--|--|
| <input type="checkbox"/> Domestic | <input type="checkbox"/> Recreational/Cultural | <input type="checkbox"/> Parks/Gardens/Plantings |
| <input type="checkbox"/> Commercial | <input type="checkbox"/> Transportation | <input type="checkbox"/> Cemetery |
| <input type="checkbox"/> Mfg/Industrial | <input type="checkbox"/> Military/Defense | <input type="checkbox"/> Monument/Statue |
| <input type="checkbox"/> Civic/Government | <input type="checkbox"/> Agricultural | <input type="checkbox"/> State Marker |
| <input type="checkbox"/> Religious | <input type="checkbox"/> Outbuilding | <input type="checkbox"/> Local Marker |
| <input type="checkbox"/> Social | <input type="checkbox"/> Cisterns/Tanks/Wells | <input type="checkbox"/> Other Marker |
| <input checked="" type="checkbox"/> Educational | <input type="checkbox"/> Petroleum | <input type="checkbox"/> Noted Architect |

Architectural Style List

- | | |
|--|--|
| <input type="checkbox"/> Spanish Colonial 1585-1821 | <input type="checkbox"/> Pueblo Revival 1910-today |
| <input type="checkbox"/> French Colonial 1608-1830 | <input type="checkbox"/> Spanish Eclectic 1915-1940 |
| <input type="checkbox"/> Greek Revival 1820-1860 | <input type="checkbox"/> Monterey 1925-1955 |
| <input type="checkbox"/> Gothic Revival 1830s-1870s | <input type="checkbox"/> Prairie 1900s-1920s |
| <input type="checkbox"/> Italianate 1840s-1880s | <input type="checkbox"/> Craftsman 1900-1930s |
| <input type="checkbox"/> Second Empire 1850s-1880s | <input type="checkbox"/> Fireproof House 1900-1930s |
| <input type="checkbox"/> Stick Style 1860s-1880s | <input type="checkbox"/> Moderne 1920-1940 |
| <input type="checkbox"/> Queen Anne 1880-1910 | <input type="checkbox"/> Art Deco 1920-1940 |
| <input type="checkbox"/> QA Spindlework 1880-1910 | <input type="checkbox"/> International 1925-today |
| <input type="checkbox"/> QA Free Classic 1880-1910 | <input type="checkbox"/> Minimal Traditional 1935-1960 |
| <input type="checkbox"/> Shingle 1880-1900 | <input type="checkbox"/> A-Frame 1930s-today |
| <input type="checkbox"/> Richardson Roman. 1880-1900 | <input type="checkbox"/> Small Ranch 1946-1980 |
| <input type="checkbox"/> Folk Victorian 1870-1910 | <input type="checkbox"/> Large Ranch 1946-1980 |
| <input type="checkbox"/> Colonial Revival 1880s-1955 | <input type="checkbox"/> Split-Level 1955-1980s |
| <input type="checkbox"/> Neoclassical 1885-1940s | <input type="checkbox"/> Contemporary 1940-1980s |
| <input type="checkbox"/> Tudor Revival 1890s-1940s | <input type="checkbox"/> Shed 1960-today |
| <input type="checkbox"/> Beaux Arts 1885-1930 | <input type="checkbox"/> Neoelectic 1965-today |
| <input type="checkbox"/> French Eclectic 1880s-1940s | <input type="checkbox"/> Prefabricated 1940s-today |
| <input type="checkbox"/> Italian Renaissance 1890-1935 | <input type="checkbox"/> Mobile House 1945-today |
| <input type="checkbox"/> Mission 1890-1940 | |

Commercial Form List

- | | |
|--|---|
| <input type="checkbox"/> One-Part Commercial Block | <input type="checkbox"/> Temple Front |
| <input type="checkbox"/> Two-Part Commercial Block | <input type="checkbox"/> Enframed Block |
| <input type="checkbox"/> Enframed Window Wall | <input type="checkbox"/> Central Block with Wings |
| <input type="checkbox"/> Stacked Vertical Block | <input type="checkbox"/> Arcaded Block |
| <input type="checkbox"/> Two-Part Vertical Block | <input type="checkbox"/> Mixed |
| <input type="checkbox"/> Three-Part Vertical Block | |

VOICES FROM SMALL PLACES HISTORIC SURVEY

| | | | | |
|-------------------------------|---------------------------------------|--------------|-------------|----|
| Porch Loc. | | | | |
| Porch Roof | | | | |
| Porch Support | | | | |
| Hist. Context | EDUCATION-Preschool/Primary/Secondary | | | |
| <u>Integrity</u> | Location | No | Design | No |
| | Materials | No | Workmanship | No |
| | Setting | No | Feeling | No |
| | Association | No | | |
| Public Access | Yes | | | |
| Threatened | Yes | Threat | Neglect | |
| <u>Ancillary Structure #1</u> | Type | | | |
| Roof Form | Roof Matls | | | |
| Wall Matls | | | | |
| <u>Ancillary Structure #2</u> | Type | | | |
| Roof Form | Roof Matls | | | |
| Wall Matls | | | | |
| <u>Site Extras</u> | Sidewalks | Terracing | | |
| | Drives | Well/Cistern | | |
| | Gardens | Other | | |
| Owner Name | | | | |
| Address | | | | |
| City | State | | | |
| Zip | Status | Private | | |

Log Structure List

- Single-pen Double-pen
 Saddlebag Dogtrot

Date Range List

- 1820-1865 1929-1945
 1865-1900 1945-1980
 1900-1929 1980-today

Overall Condition

- Excellent
 Good
 Fair
 Poor
 Bad

Vernacular List

- Hall-and-parlor (1 story) I-house (2 story)
 Shotgun (1 story) Town house (2 story)
 Massed side-gable (1) Box house (2 story)
 Massed gable-front (1) Gable front (2 story)
 Four-square (1 story) Four-square (2 story)
 Gable-front-and-wing (1) Gable-front-and-wing (2)
 Front-facing U or H (1) Front-facing U or H (2)

- Single-Crib (log) Midwest 3 Portal Flanking Shed
 Double-Crib (log) Wisconsin Dairy Hay Hood
 Side/Drive-In Crib Pole Barn Corncrib
 Transverse Frame Round/Polygonal Silo

Barn & Accessories

Voices from Small Places is a project of the Center for Regional Heritage Research, SFASU. More information about this project and other Center activities can be found at <http://www.sfasu.edu/heritagecenter/>. The full version of this survey utilizes the THC's Section 106 fields.



Notes: The building is no longer on the site.