## **VOICES FROM SMALL PLACES HISTORIC SURVEY**

Project #	CRHR-001 Property # 005					Resources Type List					
County	Shelby	Shelby City Arcadia					☐ Recreational/Cultura				
Address	119 CR 1515					☑ Domestic ☐ Commercial	☐ Transportation	Cemetery			
Recorded By	Kelley Snowden		Date	7/25/2014		☐ Mfg/Industrial	☐ Military/Defense	☐ Monument/Statue			
	Jewel Jones Ho	***************************************				- Civio Covorimion - Triginoalitarai					
						☐ Religious ☐ Social	☐ Outbuilding ☐ Cisterns/Tanks/Wells	☐ Local Marker ells ☐ Other Marker			
Historic Name						☐ Educational	☐ Petroleum	☐ Noted Architect			
<b>Date Const</b>		Estimat	ed			Architectural Style List					
Actual		Modifi	ed			Spanish Colonial 15		Revival 1910-today			
Roof Type	☑ Gable ☐ Gar	ed 🔲 (	Other			☐ French Colonial 1608-1830       ☐ Spanish Eclectic 1915-1940         ☐ Greek Revival 1820-1860       ☐ Monterey 1925-1955         ☐ Gothic Revival 1830s-1870s       ☐ Prairie 1900s-1920s         ☐ Italianate 1840s-1880s       ☒ Craftsman 1900-1930s         ☐ Second Empire 1850s-1880s       ☐ Fireproof House 1900-1930s					
Roof Materials	☐ Wood Shingles ☐ Composition Shi		Tile Metal	☐ Other							
<b>Roof Condition</b>	☐ Excellent   ☑ Good   ☐ Fair   ☐ Poor   ☐ Bad					☐ Stick Style 1860s-1880s ☐ Moderne 1920-1940 ☐ Queen Anne 1880-1910 ☐ Art Deco 1920-1940					
# of Dormers		Dorr	ner Ty	pe None	yebrow	□ QA Spindlework 1880-1910       □ International 1925-today         □ QA Free Classic 1880-1910       □ Minimal Traditional 1935-1960         □ Shingle 1880-1900       □ A-Frame 1930s-today         □ Richardson Roman. 1880-1900       □ Small Ranch 1946-1980         □ Folk Victorian 1870-1910       □ Large Ranch 1946-1980         □ Colonial Revival 1880s-1955       □ Split-Level 1955-1980s					
Trail materials	☐ Log ☑ Wood ☐ Metal ☐ Wood	tone V. Siding Shingle		☐ Hipped ☐ Ot☐ Shed☐ Flat☐ Deck☐ Arched☐							
	☐ Excellent ☐ Good ☒ Fair ☐ Poor ☐ Bad					□ Neoclassical 1885-1940s □ Contemporary 1940-1980s					
Window Type	Single/Double-Hung					☐ Tudor Revival 1890s-1940s ☐ Shed 1960-today ☐ Beaux Arts 1885-1930 ☐ Neoeclectic 1965-today					
Window Mat						☐ French Eclectic 1880s-1940s ☐ Prefabricated 1940s-today					
Orig Windows	Yes					☐ Italian Renaissance 1890-1935 ☐ Mobile House 1945-today					
Single Door	Yes	Double D	oor	No		☐ Mission 1890-1940					
Transom	No	Sideliç	ghts	No		Commercial Form L	ist				
# of Stories	1	Basem	nent	None		One-Part Commerci	al Block	ont			
Foundation	Pier and Beam			f Bays 3		☐ Two-Part Commerci					
Bldg Plan	Bungalow					☐ Enframed Window Wall ☐ Central Block with Wings					
# of Chimneys	1	Chimney	Туре	Exterior		☐ Stacked Vertical Blo ☐ Two-Part Vertical Bl		SIOCK			
Chimney Mat	Brick					☐ Three-Part Vertical I					

## **VOICES FROM SMALL PLACES HISTORIC SURVEY**

Porch Loc. Front				Log Structure List	Date Range	List Ove	erall Condition
Porch Roof Shed				☐ Single-pen ☐ Double-pen	☐ 1820-1865 ☐ 1865-1900 ☐ 1900-1929	1945-1980	☐ Excellent ☑ Good ☐ Fair
Porch Support Brick Pie	rs			☐ Saddlebag ☐ Dogtrot			
Hist. Context ARCHITE	ECTURE-Don	nestic		Vernacular List	Poor		
Integrity Location	Yes	Design	Yes	☐ Shotgun (1 story) ☐ ☐ Massed side-gable (1) ☐ ☐ Massed gable-front (1) ☐ ☐ Four-square (1 story) ☐	l I-house (2 story) l Town house (2 story) l Box house (2 story) l Gable front (2 story)		□ Bad
Materials	Yes	Workmanship Feeling	Yes				
Setting	Yes		Yes				
Association	Yes				☐ Four-square (2	story)	
Public Access Yes					d-wing (2) or H (2)		
Threatened No	Thr	eat					
Roof Form Front-Gabled Wall Matis ASBESTOS	-Siding	i	T-Other	☐ Double-Crib (log) ☐ Wisc ☐ Side/Drive-In Crib ☐ Pole	onsin Dairy 🔲 Barn 🗀	] Flanking Shed ] Hay Hood ] Corncrib ] Silo	Barn & Accessories
Roof Form Front-Gabled Wall Matls WOOD-Othe	d Roof Mar	tis WOOD-C	Other No	Voices from Small Places project of the Center for Re			
Site Extras Sidewalks Norives N		Well/Cistern	No	Heritage Research, SFASI More information about this			
Gardens N		Other	110	and other Center activities			
Owner Name				found at http://www.sfasu.edu/heritagecenter/. The f	i ill		
Address				version of this survey utiliz	- COL		1+4-2
City		State		THC's Section 106 fields.		delid makes	
Zip		Status					
	_	-	in fair condition; loned out back	Right has 1950s asbestos s	iding; left is a p	olywood raised s	tructure;