VOICES FROM SMALL PLACES HISTORIC SURVEY

Project #	CRHR-001 Property # 008					Resources Type List			
County	Shelby		Arca	dia		□ Domestic □ Domestic	☐ Recreational/Cult		
Address	CR 4059	::::::: :	.*			☐ Commercial	☐ Transportation	Cemetery	
Recorded By	Kelley Snowden		Date	7/24/2014		☐ Mfg/Industrial	☐ Military/Defense	☐ Monument/Statue	
	Amos Bryce Hor					☐ Civic/Government	Agricultural	State Marker	
Historic Name	Janes Bryce Frei					☐ Religious ☐ Social	☐ Outbuilding ☐ Cisterns/Tanks/W	☐ Local Marker /ells ☐ Other Marker	
nistoric Name						☐ Educational	Petroleum	☐ Noted Architect	
Date Const		Estimat	ed				Architectur	al Style List	
Actual		Modifi	ed			Spanish Colonial 15		eblo Revival 1910-today	
Roof Type	Gable ☐ Gambrel ☐ Flat ☐ Shed ☐ Other					☐ French Colonial 1608-1830 ☐ Spanish Eclectic 1915-1940 ☐ Greek Revival 1820-1860 ☐ Monterey 1925-1955 ☐ Gothic Revival 1830s-1870s ☐ Prairie 1900s-1920s			
Roof Materials	☐ Wood Shingles☒ Composition Shi	☐ Wood Shingles ☐ Tile ☐ Other ☑ Composition Shingles ☐ Metal				☐ Italianate 1840s-1880s ☐ Craftsman 1900-1930s ☐ Second Empire 1850s-1880s ☐ Fireproof House 1900-1930s			
Roof Condition	Excellent Good Fair ⊠ Poor Bad					☐ Stick Style 1860s-1880s ☐ Moderne 1920-1940 ☐ Queen Anne 1880-1910 ☐ Art Deco 1920-1940			
# of Dormers		Dorr	ner Ty		ebrow	☐ QA Spindlework 18		ernational 1925-today	
Trail materials	Stucco					□ QA Free Classic 1880-1910 □ Minimal Traditional 1935-1960 □ Shingle 1880-1900 □ A-Frame 1930s-today □ Richardson Roman. 1880-1900 □ Small Ranch 1946-1980 □ Folk Victorian 1870-1910 □ Large Ranch 1946-1980 □ Colonial Revival 1880s-1955 □ Split-Level 1955-1980s			
Wall Condition	☐ Excellent ☐ Good ☐ Fair ☐ Poor ☒ Bad					☐ Neoclassical 1885-1940s ☐ Contemporary 1940-1980s ☐ Tudor Revival 1890s-1940s ☐ Shed 1960-today			
Window Type	Single/Double-Hung					☐ Beaux Arts 1885-1930 ☐ Neoeclectic 1965-today			
Window Mat	Vood					☐ French Eclectic 1880s-1940s ☐ Prefabricated 1940s-today			
Orig Windows	/es					☐ Italian Renaissance 1890-1935 ☐ Mobile House 1945-today ☐ Mission 1890-1940			
Single Door	Yes	Double D	oor	No		L_1 MISSION 1090-1940			
Transom	No	Sideli	ghts	No		Commercial Form L	.ist		
# of Stories	1.5	Basem	nent	None		☐ One-Part Commerci	ial Block 🔲 Temple	e Front	
Foundation				f Bays 3		Two-Part Commerci			
Bldg Plan	T-Plan					☐ Enframed Window V		I Block with Wings	
# of Chimneys		Chimney				☐ Stacked Vertical Blo ☐ Two-Part Vertical Bl		U DIUUK	
Chimney Mat		·····				☐ Three-Part Vertical I	el e		

VOICES FROM SMALL PLACES HISTORIC SURVEY

Porch Roof Front-Gabled ☐ Single-pen ☐ Double-pen ☐ 1820-1865 ☐ 1929-1945	 ************************************
	☐ 1945-1980 ☐ Good ☐ 1980-today ☐ Fair ☐ Poor ☐ Bad Dry) (y) (y) (y) (ry) (ring (2)
Porch Silnhort: Wood Posis-Piain	
Hist. Context ARCHITECTURE-Domestic Vernacular List	
Integrity Location Yes Design No ☐ Hall-and-parlor (1story) ☐ I-house (2 story)	
Materials No Workmanship No Shotgun (1 story) Town house (2 story)	
Setting No Feeling NO Massed side-gable (1) Box house (2 story) Massed gable-front (1) Gable front (2 story)	
Association No ☐ Four-square (1 story) ☐ Four-square (2 story)	
Public Access No ☐ Gable-front-and-wing (1) ☐ Gable-front-and-wing (2) ☐ Front-facing U or H (1) ☐ Front-facing U or H (2)	
Threatened Yes Threat Neglect	
Ancillary Structure #1 Type Barn Single-Crib (log) Midwest 3 Portal Flanking Shed	
Roof Form Front-Gabled Roof Matls METAL-Corrugated Double-Crib (log) Wisconsin Dairy Hay Hood	Barn & Accessories
Wall Matls Side/Drive-In Crib ☐ Pole Barn ☐ Corncrib☐ Transverse Frame ☐ Round/Polygonal ☐ Silo	Accessories
Ancillary Structure #2 Type	
Roof Form Roof Matls	
Wall Matls Voices from Small Places is a project of the Center for Regional	
Site Extras Sidewalks No Terracing No Heritage Research, SFASU.	
Drives No Well/Cistern Yes More information about this project	
Gardens No Other and other Center activities can be	m su
Owner Name found at http://www.sfasu. edu/heritagecenter/. The full	
Address version of this survey utilizes the	
City State THC's Section 106 fields.	
Zip Status	
<u></u>	
Notes: House is in poor condition but has a rear gable wing and a back porch; there is an open well; the double-crib log condition out about 100 yards and is in poor condition - has lean-to shed room extension. This place was "chiqqer cer	