## VOICES FROM SMALL PLACES HISTORIC SURVEY

Project #	CRHR-001	Property #	010	)	Resources Type List					
County	Shelby	City	Arcad							
Address	FM 1645									
	Kelley Snowde	n I	Date	7/25/2014	Mfg/Industrial	🗌 Military	y/Defense	Monument/Statue		
		· · · · · · · · · · · · · · · · · · ·						State Marker		
		301113011			☐ Religious ☐ Social		ilding ns/Tanks/Wells	Local Marker Other Marker		
Historic Name										
Date Const		Estimate	d		Architectural Style List					
Actual		Modified				Spanish Colonial 1585-1821 Pueblo Revival 1910-today				
	🛛 Gable 🔲 Ga	ambrel 🛛 F	at		French Colonial 1608	8-1830	🗌 Spanish I	Eclectic 1915-1940		
Roof Type	Hipped St	ned 🗌 O	ther		Greek Revival 1820-		Monterey			
	U Wood Shingles	s □ <sup>.</sup>	Гile	Other	Italianate 1840s-188		· · · · · · <u>· · ·</u> · · · · · · · · · ·	n 1900-1930s		
	Composition S	hingles 🔲 l	Metal					House 1900-1930s		
Poof Condition	Excellent	Good D Fa	ir 🗖	Poor 🔲 Bad	Stick Style 1860s-18	80s	Moderne	1920-1940		
# of Dormers					Queen Anne 1880-1	********************	Art Deco			
	:	Dorm	er Typ	<b>De</b> X None ☐ Eyebrow ☐ Gabled ☐ Inset	QA Spindlework 1880-1910 International 1925-today					
Wall Materials				Hipped Other	QA Free Classic 188	80-1910	<u></u>	raditional 1935-1960		
		dstone V.		Shed	Shingle 1880-1900	1880 100	A-Frame	nch 1946-1980		
	Log Woo	od Siding		☐ Flat ☐ Deck	Folk Victorian 1870-			nch 1946-1980		
	Metal Woo	od Shingle			Colonial Revival 1880s-1955					
Wall Condition	Excellent	Good 🗌 Fa	ir 🗌	Poor Bad	Neoclassical 1885-1	940s	Contemp	orary 1940-1980s		
Window Type	Casement				Tudor Revival 1890s		Shed 196	0-today tic 1965-today		
Window Mat	Aluminum				French Eclectic 1880			ated 1940s-today		
Orig Windows	Yes				Italian Renaissance 1890-1935 Mobile House 1945-today					
Single Door	Yes	Double D		No	Mission 1890-1940					
Transom	No	Sidelig		No	Commercial Form Li	ist				
# of Stories	•	Basem		None	One-Part Commercia	al Block	Temple Front	•		
Foundation	Slab		# of	Bays 3	Two-Part Commercia		Enframed Blo			
Bida Plan	Rectangular				Enframed Window W		Central Block			
# of Chimneys		Chimney 1	vne	nterior	Stacked Vertical Blo		Arcaded Bloc	:k		
-		Ahe i		Two-Part Vertical Blo		Mixed				
Chimney Mat	Brick				Three-Part Vertical E	SIOCK				

## VOICES FROM SMALL PLACES HISTORIC SURVEY

Porch Loc. Front				Log Structure List	Date Range List	Overall Condition			
Porch Roof Shed				Single-pen Double-pen	🔲 1820-1865 🛛 1929-1945	1945-1980 🛛 Good			
Porch Support Wood	l Posts-Pla	iin		Saddlebag Dogtrot	□ 1865-1900 □ 1945-1980 □ 1900-1929 □ 1980-today				
Hist. Context ARC	HITECTUR	E-Domestic		Vernacular List					
Integrity Locat	Integrity Location Yes		esign Yes	Hall-and-parlor (1story)	] I-house (2 story)	🗌 Bad			
Mater	Materials Yes		nship Yes		Town house (2 story)				
Set	Setting Yes		eling Yes		] Box house (2 story) ] Gable front (2 story)				
	ion Yes			🗌 Four-square (1 story)	] Four-square (2 story)				
Public Access No					Gable-front-and-wing (1) Gable-front-and-wing (2)				
Threatened No Thr		Threat							
Ancillary Structure #	<u>l</u> Type			Single-Crib (log)	est 3 Portal 🛛 Flanking Shed				
Roof Form	Roof Matls			Double-Crib (log) Wisco	Barn & Accessories				
Wall Matis				Side/Drive-In Crib Pole I	Barn ☐ Corncrib d/Polygonal ☐ Silo	Accessories			
Ancillary Structure #	2 Type								
Roof Form	R	oof Matis							
Wall Matls				Voices from Small Places is project of the Center for Re					
Site Extras Sidewal	ks N0	Terracing	ı No	Heritage Research, SFASL	Tel with				
Drive	s No	Well/Ciste	ern No	More information about this					
Garder	s N0	Other		and other Center activities	can be				
Owner Name				found at http://www.sfasu. edu/heritagecenter/. The fu		AZ ANDAL			
Address				version of this survey utilize	- A STATE OF				
City		State		THC's Section 106 fields.					
Zip		Status	Private						

Notes: