VOICES FROM SMALL PLACES HISTORIC SURVEY

| Project # | CRHR-001 F | Property # | 01 | 15 | | Resources Type List | | | | |
|-----------------|--|---|--------|--|--------------|---|---|---------------------------------------|--|--|
| County | Shelby | | Arca | dia | | □ Domestic □ Domestic | ☐ Recreational/Cultu | iral Parks/Gardens/Plantings | | |
| Address | 12402 FM 1645 | | | | | ☐ Commercial | ☐ Transportation | Cemetery | | |
| Recorded By | Kelley Snowden | , <u> </u> | | | | ☐ Mfg/Industrial | ☐ Military/Defense | ☐ Monument/Statue | | |
| | 1 | | | | | ☐ Civic/Government ☐ Agricultural ☐ State Marker | | | | |
| | Van & Elba Hughes | | | | | ☐ Religious ☐ Social | ☐ Outbuilding☐ Cisterns/Tanks/We | ☐ Local Marker ells ☐ Other Marker | | |
| Historic Name | | | | | | ☐ Educational | Petroleum | □ Noted Architect | | |
| Date Const | Estimated | | | | | Architectural Style List | | | | |
| Actual | | Modifi | ed | Yes | | Spanish Colonial 15 | | blo Revival 1910-today | | |
| Roof Type | | ed 🔲 | Other | | - | ☐ French Colonial 1608-1830 ☐ Spanish Eclectic 1915-1940 ☐ Greek Revival 1820-1860 ☐ Monterey 1925-1955 ☐ Gothic Revival 1830s-1870s ☐ Prairie 1900s-1920s | | | | |
| Roof Materials | ☐ Wood Shingles ☐ Tile ☐ Other ☐ Italianate 1840s-1880s ☐ Craftsman 1900-1930s ☐ Composition Shingles ☐ Metal ☐ Second Empire 1850s-1880s ☐ Fireproof House 1900-1930s | | | | | | | | | |
| | Excellent □ G | Good F | air 🗌 |] Poor □ Bad | | ☐ Stick Style 1860s-1880s ☐ Moderne 1920-1940 ☐ Queen Anne 1880-1910 ☐ Art Deco 1920-1940 | | | | |
| # of Dormers | | Dorr | mer Ty | /pe ⊠ None □ Eye □ Gabled □ Ins | | ☐ QA Spindlework 1880-1910 ☐ International 1925-today | | | | |
| Trail materials | ☐ Log ☑ Wood ☐ Metal ☐ Wood | Siding stone V. Siding Shingle | . – | ☐ Hipped ☐ Oth ☐ Shed ☐ Flat ☐ Deck ☐ Arched | | □ QA Free Classic 1880-1910 □ Minimal Traditional 1935-1960 □ Shingle 1880-1900 □ A-Frame 1930s-today □ Richardson Roman. 1880-1900 □ Small Ranch 1946-1980 □ Folk Victorian 1870-1910 □ Large Ranch 1946-1980 □ Colonial Revival 1880s-1955 □ Split-Level 1955-1980s | | | | |
| | ☐ Excellent ☐ Good ☐ Fair ☐ Poor ☐ Bad | | | | | ☐ Neoclassical 1885-1940s ☐ Contemporary 1940-1980s ☐ Tudor Revival 1890s-1940s ☐ Shed 1960-today | | | | |
| Window Type | Single/Double-H | lung | | | | ☐ Beaux Arts 1885-1930 ☐ Neoeclectic 1965-today | | | | |
| Window Mat | | | | | | | French Eclectic 1880s-1940s Prefabricated 1940s-today | | | |
| Orig Windows | Yes | | | | | ☐ Italian Renaissance 1890-1935 ☐ Mobile House 1945-today ☐ Mission 1890-1940 | | | | |
| Single Door | Yes | Double D | Oor | No | | LI MISSION 1090-1940 | | | | |
| Transom | No | Sideli | ghts | No | | Commercial Form L | ist | | | |
| # of Stories | 1 | Basen | nent | None | | ☐ One-Part Commerci | ial Block | Front | | |
| Foundation | Pier and Beam | | # c | of Bays 3 | | Two-Part Commerci | ial Block 🔲 Enframe | ed Block | | |
| Bldg Plan | Four Square | | | | | ☐ Enframed Window V | | Block with Wings | | |
| # of Chimneys | 1 | Chimney | Туре | Interior | | ☐ Stacked Vertical Blo ☐ Two-Part Vertical Bl | | DIOCK | | |
| Chimney Mat | Brick | T | | | | ☐ Three-Part Vertical I | | | | |
| | | | | | | | | | | |

VOICES FROM SMALL PLACES HISTORIC SURVEY

| Porch Loc | c. Front | | | | Log Structure List | Date Range List | Overall Condition | |
|-----------------|------------------------|--------------|--------------|-------------|---|--|----------------------|--|
| Porch Roo | of Shed | | | | ☐ Single-pen ☐ Double-pen | ☐ 1820-1865 ☐ 1929-1945 ☐ 1865-1900 ☐ 1945-1980 ☐ 1900-1929 ☐ 1980-today | <u> </u> | |
| Porch Suppor | rt Box Co | lumns | | | Saddlebag Dogtrot | | 1+1+1+1+1+1+1+1+1+1+ | |
| Hist. Contex | ct ARCHI | TECTURE-Dor | mestic | | Vernacular List | ☐ Poor | | |
| <u>Integrit</u> | Integrity Location Yes | | Desig | n No | | I-house (2 story) | ☐ Bad | |
| | Materials | s Yes | Workmanshi | p Yes | | Town house (2 story) | | |
| | Setting | g Yes | Feeling | g Yes | | Box house (2 story) Gable front (2 story) | | |
| A | Associatio | n Yes | | | ⊠ Four-square (1 story) □ | Four-square (2 story) Gable-front-and-wing (2) | | |
| Public Acces | s No | | | | | | | |
| Threatened | d No | Th | reat | | | Front-facing U or H (2) | | |
| Ancillary Stru | ucture #1 | Type Barn | | | Single-Crib (log) Midwe | 3 Portal Flanking Shed | | |
| Roof Form FI | ront-Gabl | ed Roof Mat | ls METAL | -Corrugated | ☐ Double-Crib (log) ☐ Wiscor | nsin Dairy Hay Hood | Barn & Accessories | |
| Wall Matls W | /OOD-Bo | ard & Batten | | | Side/Drive-In Crib Pole B | arn ☐ Corncrib /Polygonal ☐ Silo | ncrib | |
| Ancillary Stru | ucture #2 | Туре | | | Transverse Frame Round | orygonal Gollo | | |
| Roof Form | | Roof Ma | tls | | | | | |
| Wall Matls | | | i | | Voices from Small Places is | a | | |
| i | | NIO | | No | project of the Center for Reg | | | |
| Site Extras | Sidewalks | : | Terracing | No | Heritage Research, SFASU. | | | |
| | Drives | į | Well/Cistern | No | More information about this and other Center activities c | | | |
| | Gardens | INO | Other | | found at http://www.sfasu. | | | |
| Owner Name | | | | | edu/heritagecenter/. The ful | and the second s | | |
| Address | | | | | version of this survey utilizes | s the | | |
| City | | | State | | THC's Section 106 fields. | | | |
| Zip | | | Status P | rivate | <u>l</u> | | | |
| Notes: | | | | | | | | |
| 14000. | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| l | | | | | | | | |