ANGELINA COUNTY TEXAS HISTORIC SURVEY

New Duplicate Find Spell Check

Project #	Property #	52	Resource Type List				
-	Angelina City Lu		Domestic	Recreationa		Parks/Gardens/Plantings	
-	0	KIII	Commercial	Transportati			
Address 113 East Lufkin Street			Mfg/Industrial	Military/Defe	ense	Monument/Statue	
Recorded By	Conor Herterich Da	te 4/3/2016	Civic/Government	Agricultural		State Marker	
Current Name	Vacant					Local Marker	
	Vaoant		Social	Cisterns/Tar	nks/Wells	Other Marker	
Historic Name			Educational	Petroleum		Shirley Simon	
Prop Type	Building Style List (Based on McAlester)						
Current Funct	VACANT		Spanish Colonial 15			n 1905-1930s	
Historic Funct COMMERCE-Business			French Colonial 160		Art Moderne 1920-1940		
Date Const	1906 Estimate		Greek Revival 1820		Art Deco		
			Gothic Revival 1830			nal 1925-today*	
Actual	No Modifie	d No	Italianate 1840-1880		<u> </u>	Traditional 1935-1955	
THC Style			Second Empire 185			1940s-1985 ated 1940s-today	
Roof Form	Flat					Small Ranch 1945-1980	
Roof Material			QA Spindlework 1880-1910s		Large Ranch 1945-1980		
			QA Free Classic 1880-1910s		Styled Ranch 1945-1985		
# of Dormers			Shingle 1880-1910s		Split-Level Form 1945-1980s		
Dormer Type				Contemporary/MCM 1945-1980s			
Wall Const	Load-Bearing Brick			Mfrd House Single 1954-today			
Wall Material	BRICK		Beaux Arts 1885-19		·····	1950s-1970s	
Window Type	Single/Double-Hung				New Formalism 1950s-1970s*		
Window Mat			Mission 1890-1930			1950s-1970s*	
	vvood		Tudor Revival 1890		Organic 1		
Orig Windows		Page Down	Neoclassical 1895-1			ern 1960s-today	
Single Door	No Double Door	Yes	French Eclectic 191 Pueblo Revival 191		Shed 196	ditional 1985-today	
Transom	No Sidelights	No	Spanish Revival 191		<u></u>	im Mansion 1985-today	
# of Stories	2 Basement	Unknown	Monterey 1925-195			Vernacular 1985-today	
Foundation			Prairie 1900s-1920s		🗌 21st C M	odern 2000-today	
			Fireproof House 190	00-1930s		* common for Commercial	
Bldg Plan	Rectangular	ular Data Banga List					
# of Chimneys	Chimney Type	□ 1820-1865	Date Range List				
Chimney Mat		□ 1820-1865 ⊠ 1900-1929 □ 1945-1980 □ 2000-today □ 1865-1900 □ 1929-1945 □ 1980-2000					

ANGELINA COUNTY TEXAS HISTORIC SURVEY

New Duplicate Find Spell Check

. .

Porch Loc.							
Porch Roof			Log Structure List				
Porch Support			Single-pen Double-pen				
Hist. Context			Saddlebag Dogtrot				
Integrity Location Yes Des		Design Yes	Vernacular House Form List	Overall Condition			
Materials	No	Workmanship Yes	Hall-and-parlor (1story)	story)			
Setting	No	Feeling No	Shotgun (1 story)	Good			
Association	Yes		 Massed side-gable (1) Box house (2 story) Massed gable-front (1) Gable front (2 story) 	□ Fair ⊠ Poor			
Public Access No			☐ Four-square (1 story) ☐ Four-square (2 story)	Bad			
Threatened Yes		Threat Neglect	Gable-front-and-wing (1) Gable-front-and-wing (2)	🗌 Vacant			
Ancillary Structure #1	Туре		Front-facing U or H (1) Front-facing U or H (2)	🔲 Gone			
Roof Form	Ro	oof Matis					
Wall Matis			Commercial Form List Reference	e Image			
<u>Site Extras</u> Sidewalks	No	Terracing No	One-Part Commercial Block				
Drives	No	Well/Cistern No	☑ Two-Part Commercial Block ☐ Enframed Window Wall				
Gardens	No	Other	Stacked Vertical Block				
Owner Name			Two-Part Vertical Block				
Address			Three-Part Vertical Block Temple Front				
City		State	Enframed Block				
Zip		Status	Central Block with Wings				
Notes:		Page Up	Mixed (based on Longstreth)				