ANGELINA COUNTY TEXAS HISTORIC SURVEY

New Duplicate Find Spell Check

Delete

Project #	Property # 44	Resource Type List
County Angelina	City Lufkin	☐ Domestic ☐ Recreational/Cultural ☐ Parks/Gardens/Plantings
Address 211 East S	•	☐ Commercial ☐ Transportation ☐ Cemetery
	•	☐ Mfg/Industrial ☐ Military/Defense ☐ Monument/Statue 16 ☐ Civic/Government ☐ Agricultural ☐ State Marker
Recorded By Conor He	terich Date 3/21/201	16 ☐ Civic/Government ☐ Agricultural ☐ State Marker ☐ Religious ☐ Outbuilding ☐ Local Marker
Current Name J.S Moore	Building	☐ Social ☐ Cisterns/Tanks/Wells ☐ Other Marker
Historic Name		☐ Educational ☐ Petroleum ☐ Shirley Simon
Prop Type Building		Style List (Based on McAlester)
Current Funct COMMER	CE-Business	☐ Spanish Colonial 1585-1821 ☐ Craftsman 1905-1930s
Historic Funct COMMER	CF-Business	French Colonial 1608-1830 Art Moderne 1920-1940
		☐ Greek Revival 1820-1860 ☐ Art Deco 1920-1940
Date Const	Estimated	Gothic Revival 1830-1870s International 1925-today*
Actual	Modified No	☐ Italianate 1840-1880s ☐ Minimal Traditional 1935-1955
THC Style		☐ Second Empire 1850-1880s ☐ Mansard 1940s-1985 ☐ Stick Style 1860-1880s ☐ Prefabricated 1940s-today
Roof Form Flat		☐ Queen Anne 1880-1910s ☐ Small Ranch 1945-1980
Roof Material		QA Spindlework 1880-1910s
# of Dormers		QA Free Classic 1880-1910s Styled Ranch 1945-1985
		☐ Shingle 1880-1910s ☐ Split-Level Form 1945-1980s ☐ Richardson Roman. 1880-1900s ☐ Contemporary/MCM 1945-1980s
Dormer Type		Folk Victorian 1870-1910s
Wall Const		☐ Colonial Revival 1880s-1955 ☐ Mfrd House Double 1970s-today
Wall Material STUCCO-	Smooth	☐ Beaux Arts 1885-1930 ☐ A-Frame 1950s-1970s
Window Type Fixed		☐ Italian Renaissance 1890-1935 ☐ New Formalism 1950s-1970s*
Window Mat Aluminum		☐ Mission 1890-1930 ☐ Brutalism 1950s-1970s*
Orig Windows	_	☐ Tudor Revival 1890s-1940s ☐ Organic 1950s-today ☐ Neoclassical 1895-1955 ☐ Postmodern 1960s-today
-		Page Down I Neoclassical 1895-1955 I Postmodern 1960s-today I French Eclectic 1910-1945 I Shed 1965-today
Single Door No	Double Door Yes	☐ Pueblo Revival 1910-today ☐ New Traditional 1985-today
Transom Yes	Sidelights No	☐ Spanish Revival 1915-1940 ☐ Mellennium Mansion 1985-today
# of Stories 2	Basement Unknown	
Foundation Slab	# of Bays	☐ Prairie 1900s-1920s ☐ 21st C Modern 2000-today ☐ Fireproof House 1900-1930s * common for Commercial
Bidg Plan Irregular		☐ Fireproof House 1900-1930s * common for Commercial
# of Chimneys	Chimney Type	Date Range List
Chimney Mat		☐ 1820-1865 ☐ 1900-1929 ☐ 1945-1980 ☒ 2000-today
Omminey Mat		□ 1865-1900 □ 1929-1945 □ 1980-2000

ANGELINA COUNTY TEXAS HISTORIC SURVEY

Delete

Duplicate Find Spell Check

Threatened No Ancillary Structure #1 Type	Design Yes Workmanship Yes Feeling Yes Threat	Log Structure List Single-pen □ Double-pen □ Saddlebag □ Dogtrot Vernacular House Form List □ Hall-and-parlor (1story) □ I-house (2 story) □ Shotgun (1 story) □ Town house (2 story) □ Massed side-gable (1) □ Box house (2 story) □ Massed gable-front (1) □ Gable front (2 story) □ Four-square (1 story) □ Four-square (2 story)	Overall Condition □ Excellent ☑ Good □ Fair
Hist. Context Integrity Location Yes Materials Yes Setting Yes Association Yes Public Access Yes Threatened No Ancillary Structure #1 Type	Workmanship Yes Feeling Yes	Vernacular House Form List ☐ Hall-and-parlor (1story) ☐ I-house (2 story) ☐ Shotgun (1 story) ☐ Town house (2 story) ☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story)	Condition ☐ Excellent ☑ Good
Integrity Location Yes Materials Yes Setting Yes Association Yes Public Access Yes Threatened No Ancillary Structure #1 Type	Workmanship Yes Feeling Yes	Vernacular House Form List ☐ Hall-and-parlor (1story) ☐ I-house (2 story) ☐ Shotgun (1 story) ☐ Town house (2 story) ☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story)	Condition ☐ Excellent ☑ Good
Materials Yes Setting Yes Association Yes Public Access Yes Threatened No Ancillary Structure #1 Type	Workmanship Yes Feeling Yes	☐ Hall-and-parlor (1story) ☐ I-house (2 story) ☐ Shotgun (1 story) ☐ Town house (2 story) ☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story)	Condition ☐ Excellent ☑ Good
Setting Yes Association Yes Public Access Yes Threatened No Ancillary Structure #1 Type	Feeling Yes	☐ Shotgun (1 story) ☐ Town house (2 story) ☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story)	⊠ Good
Association Yes Public Access Yes Threatened No Ancillary Structure #1 Type		☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story)	⊠ Good
Public Access Yes Threatened No Ancillary Structure #1 Type	Threat	☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story)	L Fair
Ancillary Structure #1 Type	Threat	☐ Four-square (1 story) ☐ Four-square (2 story)	☐ Poor
Ancillary Structure #1 Type	Threat	□ Oakla faast and wide (4) □ Oakla faast and wide (6)	□ Poor □ Bad
		☐ Gable-front-and-wing (1) ☐ Gable-front-and-wing (2) ☐ Front-facing U or H (1) ☐ Front-facing U or H (2)	☐ Vacant
Roof Form		☐ Front-facing U or H (1) ☐ Front-facing U or H (2)	☐ Gone
	Roof Matls		
Wall Matis		Commercial Form List Reference	e Image
Site Extras Sidewalks No	Terracing No	One-Part Commercial Block	
Drives No	Well/Cistern No	☐ Two-Part Commercial Block ☐ Enframed Window Wall	
Gardens No	Other	☐ Stacked Vertical Block	
Owner Name		Two-Part Vertical Block	
Address		☐ Three-Part Vertical Block ☐ Temple Front	
City	State	☐ Ferripie Front ☐ Enframed Block	
Zip	Status	☐ Central Block with Wings ☐ Arcaded Block ☐ Mixed	
Notes:	Page Up	(based on Longstreth)	