ANGELINA COUNTY TEXAS HISTORIC SURVEY

Delete

New	Duplicate	Find	Spell Check
11011	- apricate		орон онови

Project #	Property # 43	3		Resour	ce Type List	
County A	ingelina City Lufk	in	Domestic	Recreation		Parks/Gardens/Plantings
-	22 East Shepherd Street		☐ Commercial ☐ Mfg/Industrial	☐ Transporta ☐ Military/Def		☐ Cemetery ☐ Monument/Statue
	•	0.104.1004.0	☐ Mig/industrial ☐ Civic/Government	☐ Agricultural		☐ State Marker
Recorded By C	Conor Herterich Date	3/21/2016	Religious	☐ Outbuilding		Local Marker
Current Name L	ufkin Municipal Court		☐ Social	☐ Cisterns/Ta		Other Marker
Historic Name			☐ Educational	☐ Petroleum		☐ Shirley Simon
Prop Type B	uilding			Style List (Ba	sed on McAl	ester)
Current Funct C	OVERNMENT-Courthouse		☐ Spanish Colonial 15			n 1905-1930s
Historic Funct	GOVERNMENT-Courthouse		☐ French Colonial 160		· · · · · · · · · · · · · · · · · · ·	rne 1920-1940
		NI.	Greek Revival 1820		Art Deco	
Date Const 2		-	Gothic Revival 1830			nal 1925-today*
Actual Y	es Modified	No	☐ Italianate 1840-188			raditional 1935-1955
THC Style F	REVIVALS-Neoclassical		☐ Second Empire 1850-1880s ☐ Mansard 1940s-1985 ☐ Stick Style 1860-1880s ☐ Prefabricated 1940s-today			
Roof Form F	ront-Gabled		Queen Anne 1880-			nch 1945-1980
Roof Material			QA Spindlework 1			nch 1945-1980
# of Dormers			QA Free Classic 1			Ranch 1945-1985
			☐ Shingle 1880-1910s			el Form 1945-1980s
Dormer Type			☐ Richardson Roman ☐ Folk Victorian 1870			orary/MCM 1945-1980s se Single 1954-today
Wall Const L	oad-Bearing Brick		Colonial Revival 18			se Double 1970s-today
Wall Material E	RICK		Beaux Arts 1885-19			1950s-1970s
Window Type F	ixed		Italian Renaissance	1890-1935	· · · · · · · · · · · · · · · · · · ·	nalism 1950s-1970s*
Window Mat △	Juminum		☐ Mission 1890-1930 ☐ Tudor Revival 1890	o 1010o		1950s-1970s*
Orig Windows		Pega Dawa	☐ Neoclassical 1895-		☐ Organic 1	ern 1960s-today
Single Door N	Double Door	Page Down	French Eclectic 191		☐ Shed 196	
•	-		☐ Pueblo Revival 191		<u></u>	litional 1985-today
Transom Y	es Sidelights	Yes	Spanish Revival 19			ım Mansion 1985-today
# of Stories 1	Basement	Unknown	Monterey 1925-195			Vernacular 1985-today
Foundation S	lab # of Bays		☐ Prairie 1900s-1920s☐ Fireproof House 19		☐ 21st C M	odern 2000-today * common for Commercial
Bldg Plan F	Rectangular		□ Filebiooi ⊓ouse 19	00-18508		
# of Chimneys	Chimney Type			Date I	Range List	
-	Chilling Type		□ 1820-1865 □ 19	00-1929 🔲 19	945-1980	☑ 2000-today
Chimney Mat			□ 1865-1900 □ 19	29-1945 🗌 19	980-2000	

ANGELINA COUNTY TEXAS HISTORIC SURVEY

Delete

Duplicate Find Spell Check

Threatened No Ancillary Structure #1 Type	Design Yes Workmanship Yes Feeling Yes Threat	Single-pen	Overall Condition Excellent Good Fair Poor Bad			
Hist. Context Integrity Location Yes Materials Yes Setting Yes Association Yes Public Access Yes Threatened No Ancillary Structure #1 Roof	Workmanship Yes Feeling Yes	Vernacular House Form List ☐ Hall-and-parlor (1story) ☐ I-house (2 story) ☐ Shotgun (1 story) ☐ Town house (2 story) ☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story) ☐ Gable-front-and-wing (1) ☐ Gable-front-and-wing (1)	Condition ☑ Excellent ☐ Good ☐ Fair ☐ Poor			
Integrity Location Yes Materials Yes Setting Yes Association Yes Public Access Yes Threatened No Ancillary Structure #1 Roof	Workmanship Yes Feeling Yes	Vernacular House Form List Hall-and-parlor (1story) I-house (2 story) Shotgun (1 story) Town house (2 story) Massed side-gable (1) Box house (2 story) Massed gable-front (1) Gable front (2 story) Four-square (1 story) Four-square (2 story) Gable-front-and-wing (1) Gable-front-and-wing (2	Condition ☑ Excellent ☐ Good ☐ Fair ☐ Poor			
Materials Yes Setting Yes Association Yes Public Access Yes Threatened No Ancillary Structure #1 Roof Form Roof	Workmanship Yes Feeling Yes	☐ Hall-and-parlor (1story) ☐ I-house (2 story) ☐ Shotgun (1 story) ☐ Town house (2 story) ☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story) ☐ Gable-front-and-wing (1) ☐ Gable-front-and-wing (1)	Condition ☑ Excellent ☐ Good ☐ Fair ☐ Poor			
Setting Yes Association Yes Public Access Yes Threatened No Ancillary Structure #1 Roof Form Roof	Feeling Yes	☐ Shotgun (1 story) ☐ Town house (2 story) ☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story) ☐ Gable-front-and-wing (1) ☐ Gable-front-and-wing (2 story)	☐ Good ☐ Fair ☐ Poor			
Association Yes Public Access Yes Threatened No Ancillary Structure #1 Roof Form Roof	_	☐ Massed side-gable (1) ☐ Box house (2 story) ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Four-square (2 story) ☐ Gable-front-and-wing (1) ☐ Gable-front-and-wing (2)	☐ Good ☐ Fair ☐ Poor			
Public Access Yes Threatened No Ancillary Structure #1 Roof Form Roof	Threat	 ☐ Massed gable-front (1) ☐ Gable front (2 story) ☐ Four-square (1 story) ☐ Gable-front-and-wing (1) ☐ Gable-front-and-wing (1) 	☐ Poor			
Threatened NO <u>Ancillary Structure #1</u> Type Roof Form Roo	Threat	☐ Four-square (1 story) ☐ Four-square (2 story) ☐ Gable-front-and-wing (1) ☐ Gable-front-and-wing (140 40 40 40 40 40 40 40 40 40 40 40 40 4			
Ancillary Structure #1 Type Roof Form Roo	Threat		L J Bau			
Roof Form Room		L LECONT TOCKNOLL OF H /1\ L LECONT TOCKNOLL OF H //	ndada ka nimyynnadia			
		☐ Front-facing U or H (1) ☐ Front-facing U or H (2)) ☐ Gone			
Wall Matis	f Matis					
Tull india		Commercial Form List Refere	ence Image			
Site Extras Sidewalks No	Terracing No	One-Part Commercial Block				
Drives No	Well/Cistern No	☐ Two-Part Commercial Block ☐ Enframed Window Wall				
Gardens No	Other	Stacked Vertical Block				
Owner Name		☐ Two-Part Vertical Block				
Address		☐ Three-Part Vertical Block ☑ Temple Front				
City	State	☐ Enframed Block				
Zip	Status	☐ Central Block with Wings ☐ Arcaded Block ☐ Mixed				
Notes:	Page Up	(based on Longstreth)				